

● PRINTER RUSH ●
(PTO ASSISTANCE)

Application : 10759934 Examiner : Lea-Edmonds GAU : 2835


From: J.Robbins Location: IDC FMF FDC Date: 9-27-05

Tracking #: Epm 10759934 Week Date: 8-15-05

DOC CODE	DOC DATE	MISCELLANEOUS
<input type="checkbox"/> 1449	_____	<input type="checkbox"/> Continuing Data
<input type="checkbox"/> IDS	_____	<input type="checkbox"/> Foreign Priority
<input type="checkbox"/> CLM	_____	<input type="checkbox"/> Document Legibility
<input type="checkbox"/> IIFW	_____	<input type="checkbox"/> Fees
<input type="checkbox"/> SRFW	_____	<input type="checkbox"/> Other
<input checked="" type="checkbox"/> DRW	<u>9-8-05</u>	
<input type="checkbox"/> OATH	_____	
<input type="checkbox"/> 312	_____	
<input type="checkbox"/> SPEC	_____	

[RUSH] MESSAGE: ATTN: Chief draftsperson

Drawings 98-05 is missing identifier label
for Fig. 1.

Thank You


[XRUSH] RESPONSE:

Drawing Corrected

INITIALS: 

NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.

REV 10/04

10/759,934

AUS920030870US1
Kulvir Singh Bhogal, et al
Combination Power Cord and Computer Security System



1/2




Fig. 1




Fig. 2